

4 ALBERT EMBANKMENT LONDON SE1 7SR

Telephone: +44 (0)20 7735 7611 Fax: +44 (0)20 7587 3210

MSC.1/Circ.1503/Corr.1 21 September 2016

ECDIS – GUIDANCE FOR GOOD PRACTICE

Corrigendum

MSC.1/Circ.1503, annex:

- 1 In paragraph 4, the following text should be deleted:
 - ", the seven IMO ECDIS-related circulars that have been replaced".
- 2 In paragraph 27.8, "paragraph 7" should read "sub-paragraph 6".
- 3 In appendix 3, paragraph 23, last sentence, "section B-I/1" should read "section B-I/12".

