



---

## TECHNICAL ALERT No. 16-64

---

### IMCA Safety Flashes 34/16 & 35/16

---

#### 1. Introduction

- 1.1. New Safety Flashes have been issued by the International Marine Contractors Association (IMCA).
- 1.2. The Bahamas Maritime Authority wishes to bring the information referenced in Paragraph 2 to the attention of interested parties<sup>1</sup>.

#### 2. IMCA Safety Flashes 34/16 & 35/16

- 2.1. Safety Flash 34/16 is available for download from the IMCA website at:

<http://www.imca-int.com/media/279203/imcasf34-16.pdf>

- 2.2. IMCA Safety Flash 34/16 – December 2016, summarises the following:

- i. *Offshore Crane Safety Systems*
- ii. *Dropped Object Near Miss: Crane Rest Damage*
- iii. *Near Miss - Dropped Steel Plate*
- iv. *Fatal Fall from Height*
- v. *High Potential Near Miss: Failure in Safety Gate*

- 2.3. Safety Flash 35/16 is available for download from the IMCA website at:

<http://www.imca-int.com/media/279375/imcasf35-16.pdf>

---

<sup>1</sup> This Technical Alert is provided by the Bahamas Maritime Authority with the aim of highlighting incidents, lessons learnt and to increase awareness, which may help avoid similar incidents occurring elsewhere. Any queries on the content of the information provided should be referred to the party providing the information.

2.4. IMCA Safety Flash 35/16 – December 2016, summarises the following:

- i. Fire in Engine Room*
- ii. Awareness: CO2 Flooding System Activation Points*
- iii. Corrosion Damage – Failed Fire Hydrant*
- iv. Fuel Spill During in Port Bunkering*
- v. Incidents in Small Workboats Used in the Offshore Renewables Sector*
- vi. First Aid Injury – Person Scalded by Steam Condensate*

### **3. Validity**

3.1. This alert is valid until further notice.

### **4. Revision History**

Rev.0 (20 December 2016) – First issue